

“TRANSLATED FROM KANNADA TO ENGLISH”

Government of Karnataka
Department of Public Works.

Ref:SaKaA/PWD/No.1SD/Ramanagara.2022-23/216. Date:28/06/2022
Office of the Assistant Executive Engineer
Public Works Department, No.1, Sub Division
Ramanagara.

To,
Chairman
The San Global School,
No.46, Hanumanthanagar,
Machanayakanahalli (Post)
Bidadi Hobli, Ramanagara Taluk.


Sir.

Sub: Issue of **Building Safety Certificate** to the building in which
The San Global School is running at Hanumanthanagar,
Machanayakana halli (Post).Bidadi Hobli,
Ramanagara Taluk.-Regarding.

- Ref:1. Your letter No.27.06.2022
2. Academic Report of Civil Engineering Branch of
Bangalore University Dated:26.06.2022.
3. Additional Secretary to Government ,Public Work
Department, Bangalore Circular No. PW 59 BED 2019
Dated: 07.05.2022
4. This office Letter no. SaKaA/PWD/No.1SD/Ramanagar/
2022-23/ Dated: 27/06/2022.

With reference (1) of the above , you have requested to
issue Building safety certificate to building Comprising of Ground Floor
and First floor situated at Hanumanthanagar, Machanayakana halli (Post).
Bidadi Hobli, Ramanagara Taluk in which The San Global School is
running .


Civil Engineering Branch of Bangalore University has
Conducted Hammer test and Ultrasonic Pulse Velocity test and other tests
on the building Comprising of Ground Floor and First floor and Civil
Engineering Branch of Bangalore University reported that the “**Building
is Stable**” as per reference (2) of above.



Joint Inspection was conducted on the Building with the Presence of the Principal of the School on 27/06.2022.

On the Basis of report of Civil Engineering Branch of Bangalore University in respect of “**Building Stability**” of the Building, as per circular of the Government under reference (4) of above, it was instructed to prescribed fee to issue Building Safety Certificate on 28.06.2022 of Rupees 10.000/- through DD to this office against the Constructed Building Comprising of Civil Engineering Branch of Bangalore University. **Building Safety Certificate has been issued** to the Building subject and measure to rectify the following Conditions:

1. Plastering and Painting at some locations to Existing Roof Slab and Walls.
2. Damp proofing works at All floors.
3. Crack sealing or grouting works at visible structural cracks at some locations.
4. Crack sealing works at visible hairline cracks at some locations of wall and column/ Beam junctions.
5. Damp proofing works to Toilet Block and repair works to avoid leakages in sanitary lines.
6. Safety Measures for Students and others.
7. Grill work to staircase & Corridor area.
8. This certificate is not valid in case of any kind of natural disaster like cyclone & Earthquake /Man –made disaster, any addition & alteration of Building.
9. No Structural Modification shall be entertained in any floors.
10. This Certificate is valid for 3 years.
11. Water tanks are fire water tanks shall be placed on the place for which it is designed by considering the water tank load.
12. This Certificate is issued to conduct classes in the existing building not to construct additional floor of building.
13. PWD is not responsible on the Ownership of the Building.



-3-

Other than this in respect of Non Structural Elements (Infrastructural facilities) School has to Obtain NOC from Civil Engineer, Medical officer , Revenue officer, Psychiatrist and Local Fire officer to get “ Fire Safety Certificate”.

Yours Faithfully

Sd/-

Assistant Executive Engineer
Public Works Department, No.1, Sub Division
Ramanagara.

Translated by me

ATTESTED BY ME

[Handwritten Signature]
K. V. BACHI REDDY, B.A., LL.B.,
ADVOCATE & NOTARY
102, Sri Krishna Building, Avenue Road,
BENGALURU - 560 002.



*My Terms Expires on
7th February 2025*

ಕರ್ನಾಟಕ ಸರ್ಕಾರ

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂಖ್ಯೆ:ಸಕಾಲ/ಲೋಇ/ನಂ.1ಉವಿ/ರಾಮನಗರ/2022-23/016 ದಿನಾಂಕ: 23/06/2022

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ ರವರ ಕಛೇರಿ

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1 ಉಪ ವಿಭಾಗ,

ರಾಮನಗರ.

ರವರಿಗೆ:

Chairman,

The San Global School,

No. 46, Hanumanthanagara,

Machanakanahalli (Post),

Bidadi Hobli, Ramanagara Taluk.

ಮಾನ್ಯರೇ,

ವಿಷಯ: ರಾಮನಗರ ತಾಲ್ಲೂಕು ಬಿಡದಿ ಹೋಬಳಿ ಮಂಚನಾಯಕನಹಳ್ಳಿ ಪೋಸ್ಟ್ ಹನುಮಂತನಗರದಲ್ಲಿರುವ The San Global School ನಡೆಸಲು ಉದ್ದೇಶಿಸಿರುವ ಕಟ್ಟಡಕ್ಕೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ: 1 ತಮ್ಮ ಪತ್ರ ಸಂಖ್ಯೆ: 27.06.2022
2 ಬೆಂಗಳೂರು ವಿಶ್ವವಿದ್ಯಾನಿಲಯದ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ಶಾಖೆಯ ಪ್ರಾಧ್ಯಾಪಕ ವಿಭಾಗ ರವರ ವರದಿ ದಿನಾಂಕ: 26.06.2022.
3 ಸರ್ಕಾರದ ಅಪರ ಕಾರ್ಯದರ್ಶಿ, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಕರ್ನಾಟಕ ಸರ್ಕಾರ ಬೆಂಗಳೂರು ರವರ ಸುತ್ತೋಲೆ ಪತ್ರ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019 ದಿನಾಂಕ: 07.05.2022
4 ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ: ಸಕಾಲ/ಲೋಇ/ನಂ.1ಉಪವಿಭಾಗ/ರಾಮನಗರ/2022-23/ ದಿನಾಂಕ: 27.06.2022.

*_*_*_*_*_*_*_*

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ರಾಮನಗರ ತಾಲ್ಲೂಕು ಬಿಡದಿ ಹೋಬಳಿ ಮಂಚನಾಯಕನಹಳ್ಳಿ ಪೋಸ್ಟ್ ಹನುಮಂತನಗರದಲ್ಲಿರುವ The San Global School ನಡೆಸಲು ಉದ್ದೇಶಿಸಿರುವ ಕಟ್ಟಡಕ್ಕೆ ನೆಲ ಮಹಡಿ ಹಾಗೂ ಮೊದಲನೇ ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ಎರಡು ಅಂತಸ್ತಿನ ಕಟ್ಟಡಕ್ಕೆ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪತ್ರವನ್ನು ನೀಡಲು ಉಲ್ಲೇಖ (1) ರ ಪತ್ರದಲ್ಲಿ ಕೋರಿರುತ್ತೀರಿ.

ಬೆಂಗಳೂರು ವಿಶ್ವವಿದ್ಯಾನಿಲಯದ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ಶಾಖೆಯ ಪ್ರಾಧ್ಯಾಪಕ ವಿಭಾಗ ರವರು ನೆಲ ಮಹಡಿ ಹಾಗೂ ಮೊದಲನೇ ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ಎರಡು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವನ್ನು ತಪಾಸಣೆ ನಡೆಸಿ, ರಿಬೋಂಡ್ ಹ್ಯಾಮರ್ ಟೆಸ್ಟ್ ಮತ್ತು ಅಲ್ಟ್ರಾಸೌನಿಕ್ ಪಲ್ಸ್‌ವೆಲಾಸಿಟಿ ಟೆಸ್ಟ್ ಹಾಗೂ ಇನ್ನಿತರೆ ಟೆಸ್ಟ್‌ಗಳನ್ನು ಮಾಡಿ ಬೆಂಗಳೂರು ವಿಶ್ವವಿದ್ಯಾನಿಲಯದ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗ ರವರು ವರದಿಯನ್ನು ನೀಡಿದ್ದು, ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವು "Structurally Stable" ಇರುವುದಾಗಿ ಉಲ್ಲೇಖ ಪತ್ರ (2) ರಲ್ಲಿ ವರದಿ ನೀಡಿರುತ್ತಾರೆ.

ದಿನಾಂಕ: 27.06.2022 ರಂದು ಸದರಿ ಕಟ್ಟಡವನ್ನು ಶಾಲಾ ಪ್ರಾಂಶುಪಾಲರು ರವರೊಡನೆ ಜಂಟಿಯಾಗಿ ತಪಾಸಣೆ ನಡೆಸಲಾಯಿತು.

ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗ, ಬೆಂಗಳೂರು ವಿಶ್ವವಿದ್ಯಾನಿಲಯ ರವರ ವರದಿಯಲ್ಲಿ ಸದರಿ ಕಟ್ಟಡದ ನೆಲ ಮಹಡಿ ಹಾಗೂ ಮೊದಲನೇ ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ಎರಡು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವು Structurally ತೃಪ್ತಿಕರವಾಗಿರುತ್ತದೆ ಎಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ ಹಾಗೂ ಉಲ್ಲೇಖ ಪತ್ರ (5) ರಲ್ಲಿ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆಯಂತೆ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಶುಲ್ಕವನ್ನು ಸೂಚಿಸಿದನ್ವಯ ದಿ: 28.06.2022 ರಂದು

ರೂ. 1000.00 ಗಳ ಡಿ.ಡಿ ಯನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುವ ಪ್ರಯುಕ್ತ ಸದರಿ ಶಾಲಾ ಆವರಣದಲ್ಲಿ ನಿವರ್ತನೆಯಾಗಿರುವ ನೆಲ ಮಹಡಿ ಹಾಗೂ ಮೊದಲನೇ ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಂತೆ ಒಟ್ಟು ಎರಡು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವು ವೈಶಿಷ್ಟ್ಯಕ್ಕೆ "Structurally Stable" ಇದೆ ಎಂದು ಕಟ್ಟಡ ಸುರಕ್ಷಾ ಪತ್ರವನ್ನು ಈ ಕೆಳಕಂಡ ನಿಬಂಧನೆಗಳೊಳಗೆ ಹಾಗೂ ಈ ಕೆಳಕಂಡ ನ್ಯೂನತೆಗಳನ್ನು ಕಾಲ ಕಾಲಕ್ಕೆ ಅಳವಡಿಸಿಕೊಳ್ಳಲು ಸೂಚಿಸಿ ನೀಡಲಾಗಿದೆ.

1. Plastering and Painting at some locations to Existing Roof slab and walls.
2. Damp proofing works at All floors.
3. Crack sealing or grouting works at visible structural cracks at some locations.
4. Crack sealing works at visible hairline cracks at some locations of wall and Column/ Beam Junctions.
5. Damp proofing works to Toilet Block and repair works to avoid leakages in Sanitary lines.
6. Safety Measures for Students and others.
7. Grill work to staircase & Corridor area.
8. This certificate is not valid incase of any kind of natural disaster like cyclone & Earth quake/ Man-made disaster, any addition & alteration of Building.
9. No Structural Modification shall be entertained in any floors.
10. This Certificate is valid for 3 years.
11. Water tanks are fire water tanks shall be placed on the place for which it is designed by considering the water tank load.
12. This Certificate is issued to conduct classes in the existing building not to construct additional floor of building.
13. ಸ್ವತ್ತಿನ ಮಾಲಿಕತ್ವದ ಹಕ್ಕಿನ ಬಗ್ಗೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಜವಾಬ್ದಾರಾಗಿರುವುದಿಲ್ಲ.

ಉಳಿದಂತೆ ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ Non- structural Elements (Infrastructural facilities) ಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಸಿವಿಲ್ ಇಂಜಿನಿಯರ್, ಆರೋಗ್ಯಾಧಿಕಾರಿ, ಕಂದಾಯ ಅಧಿಕಾರಿ, ಮನಶಾಸ್ತ್ರಜ್ಞ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ ಸ್ಥಳೀಯ ಸಂಸ್ಥೆಯ ಅಧಿಕಾರಿಗಳನ್ನೊಳಗೊಂಡ ಪರಿಷ್ಕಾ ತಂಡದ ವತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು ಪಡೆಯತಕ್ಕದ್ದು ಹಾಗೂ "Fire safety Certificate" ಅನ್ನು ಮುಖ್ಯ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿಯಿಂದ ಪಡೆಯತಕ್ಕದ್ದು.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1 ಉಪವಿಭಾಗ,
ರಾಮನಗರ.